

MISSOURI DEPARTMENT OF HEALTH STATE PUBLIC HEALTH LABORATORY

DATAMASTER MAINTENANCE REPORT

RECEIVED DHSS Breath Alcohol Program By Carol Day at 6:28 am, Sep 11, 2009

Complete this report in duplicate at the time of the regular is repaired. Send copy to Department of Health; retain original terms of the sequence of the regular terms of the sequence of the regular terms of the regular	ular monthly preventive maintenance check, and whenever instrument linal in department file.				
DATAMASTER SN	DATE OF INSPECTION				
2002.08 LOCATION OF INSTRUMENT (STREET AND CITY)	8/31/09				
Troop C HQ, Weldon Springs, MO	TIME OF INSPECTION				
CHECKLIST: Place a check (✓) to the left of each item if in observed values where determined.) Unchecked items m	found to be satisfactory or if operating within established limits. (Write				
DIAGNOSTIC CHECK (PRINTOUT ATTACHED)					
L COMPUTER	DETECTOR				
☐ PROGRAM	FILTERS				
HEATERS SAMPLE CHAMBER 49 °C	<u>49</u> °C				
☐ FLOW DETECTOR	Calibration Calibration				
☐ PUMP HIGH SPEED	D PRINTER				
☑ INDICATOR LIGHTS					
TIME AND DATE					
SIMULATOR TEMPERATURE (34 °C ± 0.2°C)	1.0°C				
CALIBRATION CHECK - Run three tests using a standard solution. All three spread of .005 or less. Check the box corresponding RECIRCULATION PUMP) 0.100% STANDARD - MUST READ BETWEEN 0.095	tests must be within \pm 5% of the standard value and must have a to the standard solution being used. (PRINTOUT ATTACHED) (USE				
O.040% STANDARD - MOST READ BETWEEN 0.038 O.040% STANDARD - MUST READ BETWEEN 0.038 (ONLY ONE STANDARD IS TO BE USED PER MAINTI	3% and 0.042% INCLUSIVE				
TEST 1	0.101 TEST 3 P 0.102				
PERFORM R.F.I. TEST (PRINTOUT ATTACHED)					
NUMBER OF REFUSALS, SINCE LAST MAINTENANCE FOLLOWS: (DO NOT INCLUDE SIMULATOR TESTS)	REPORT, AND NUMBER OF BREATH TESTS IN EACH RANGE AS				
REFUSALS N/A (004) N/A (.0509) N/A	(.1014) N/A (.1519) N/A (Over .19) N/A				
List any new parts and describe any alteration or modifical and within established limits (use other side if necessary) Replaced old software with new (04-07-2009) software. Adjusted voltages.	tion that was made to restore the instrument to operate satisfactorily				
INSDECTING OFFICER					
INSPECTING OFFICER SIGNATURE	PRINT NAME Brian M. Lutmer				
19PE II PERMIT NUMBER/EXPIRATION DATE 120145/06-19-2011	TELEPHONE NUMBER (573) 840-9140				



CERTIFICATE OF ANALYSIS

Certified Alcohol Reference Solution for Simulator

Random Samples of Lot Number 09120 of Alcohol Reference Solution for Simulator were analyzed by gas chromatography and found to contain 0.1198 percent (w/vol) ethyl alcohol. The expiration date for this lot number is April 8, 2010 at 11:59 PM.

When used in a calibrated Simulator, operating at 34°C +/- .2°C, this solution will give a breath alcohol analysis instrument reading of 0.10 percent BAC.

The alcohol and water used in this solution were free of test interfering substances.

Ted L. Pauley, President GUTH LABORATORIES, INC.

Face This Side Down - This Edge In First

BAC DataMaster Evidence Ticket

STATE OF MISSOURI ELLISVILLE POLICE DEPARTMENT

DATAMASTER SERIAL NUMBER 288288 88/31/89

EXPIRATION DETE: 86/19/11 PERMIT NUMBER: 928145 GUTH 0.10 LOT 09120 EXP. 18TE 4/8/10 MISCELLANEOUS DATA: LUTRIEN DELIGINA ESTING OFFICER: OFFICER I.D. :

--- SUPERVISOR MODE

11. 4.	() 당 ::		4:15	77.74	11:45	11:40	11:46
888	VERIFIED	00 00	<u>5</u> 5 5	101	ය ක ක	10 20 7	200
BLANK TEST				TENDENDE STREET	MERCH HONH	DECOZETO JESTELXII	WINEY LENT

11 . 10000 MIN. II. (O) H 3,00

Operator Signature

Face This Side Down - This Edge In First

BAC DataMaster Evidence Ticket

STATE OF MISSOURI ELLISVILLE POLICE DEPARTMENT

38C DATAMASTER SERIAL NUMBER 200208 (f) (f) 22 24 24 24 24

--- DIRBNOSTIC CHECK

OKEY OKEY COMPUTER: XEYS アドロの天氏な への4ーのソーののののン:

上門に開設

の元が上、 いこのとののの。

り い す

OKAY FLOW DETECTOR:

SXB7 THOS COURTS

à. Yo DETECTOR:

FILTERS:

OKBY CHI DESCRIPTIONS

OKEY

GURRIN NIRGHRUS

PRINTER TEXT

HICKLMADPORSTOVSKYZZZZZZ Benderghickinno THE PRINCIPAL BADD

Operator Signature_

Ģ

2208-02

Face This Side Down - This Edge In First

BAC DataMaster Evidence Ticket

STATE OF MISSOURI ELLISVILLE POLICE DEPARTMENT

BAC DATAMASTER SERIAL NUMBER 200208 88731788

FRRENT TIME: DOLLO SUBLECT NAME:

DOB: 11/11/11

SEX: Exit

ARRENTING OFFICERS STATE/D.L.: MO/

LUTMER/BRIEN

TESTING CHRICER: OFFICER 1.D.:

UUTMER/BRIEN/M

PERMIT NUMBER: 920145 OFFICER I.D.:

EXPIRATION DETE: 06/19/11 MISCELLANEOUS DATA: --- BREATH ANALYSIS ---

VERIFIED , <u>0</u>000 INTERNAL STANDARD SUBJECT SAMPLE BLANK TEST

11:48

. 2000 0

RADIO INTERFERENCE

200

Operator Signature_

State of Missouri DEPARTMENT OF HEALTH



PERMIT TYPE II



BRIAN M LUTMER

is hereby authorized to instruct and supervise operators, train instructors, inspect, calibrate, perform field repairs, and operate the following breath analyzer(s):

DATAMASTER; INTOXILYZER 5000; ALCO-SENSOR IV/RBT IV

for the determination of the alcoholic content of blood from a sample of expired (alveolar) air. Issued under the provisions of sections 577.020 through 577.041, RSMo 1986.

Date 06/19/09	John of Mathewson				
Number 920145 06/19/2011 Expires	Director of State Public Health Laboratory				
	Mayart T. Downelly				
	Director, Department of Health				
MO 580-0771 (7-88)	Lab. 4 (R7-88)				